	Туре	L #	Hits	Search Text	
1	BRS	L1	35	antenna same tun\$3 same electronic same switch\$3 same capacitor	
2	BRS	L2	92	antenna same electronic same switch\$3 same capacit\$4 same tun\$3	

	DBs	Time Stamp	Comments	Error Definition
1	EPO; JPO; DERWENT	2004/06/28 09:39		
2	USPAT; US-PGPUB	2004/06/28 09:52		